



AMERISPEC[®]
HOME INSPECTION SERVICE
Number One in North America



Earth/wood contact at deck



Tree too close to siding and foundation



Moisture damage at covered patio



Flex gas line into furnace cabinet