



AMERISPEC[®]
HOME INSPECTION SERVICE
Number One in North America



Pest damage at family room ceiling



Unsupported supply line in crawlspace



Crushed ducting in crawlspace